Getinge Assured

GETINGE 🛠

Bowie-Dick Test Card TT Interpretation Guide



Pass

BOWIE-DICK TEST CARD TT



AIR REMOVAL & STEAM PENETRATION TEST

Complete colour change from purple to green, indicates that an effective steam sterilization cycle has been achieved.

Fail

GETINGE

GETINGE GROUP



AIR REMOVAL & STEAM PENETRATION TEST

This is an example of one type of fail. Any remaining purple indicates a fail.

© 2023 Getinge Australia Pty Ltd ABN 67 009 673 518 Australian Phone: 1800 438 464 Email: sales.au@getinge.com New Zealand Phone: 0800 1 438 464 Email: sales.nz@getinge.com

www.getinge.com/anz

ANZ_SW_V2_044_0721 EXP 07/26